


Many damages on the 552 double sided System

1. Screws on the top are rusty



2. Both frames on both sides are not well painted



3. the door not closed well



4. much damages on the painting

